



ARKANSAS POWER & LIGHT COMPANY
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

August 31, 1979

2-089-19

Mr. K. V. Seyfrit, Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2
Docket No. 50-368
License No. NPF-6
Reportable Occurrence Report
Nos. 50-368/79-063; 50-368/79-065;
and 50-368/79-066
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, we have attached the subject reports concerning the failure of an isolation valve to indicate closure during a stroke test (50-368/79-063); the failure of a battery charger to perform (50-368/79-065); and the inoperability of an isolation valve to fully close on the Reactor Drain Tank (50-368/79-066).

Very truly yours,

David C. Trimble
Manager, Licensing

DCT:REI:vb

Attachment

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and
Enforcement
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

Mr. W. D. Johnson
U. S. Nuclear Regulatory Comm.
P. O. Box 2090
Russellville, AR 72801

Mr. Norman Haller, Director
Office of Management and
Program Analysis
U. S. Nuclear Regulatory Comm.
Washington, D. C. 20555

956237

7909170388