DUKE POWER COMPANY

POWER BUILDING
422 SOUTH CHURCH STREET, CHARLOTTE, N. C. 28242

WILLIAM O. PARKER, JR. VICE PRESIDENT STEAM PRODUCTION

August 20, 1979

TELEPHONE, AREA 704 373-4083

Mr. J. P. O'Reilly, Director U.S. Nuclear Regulatory Commission Region II 101 Marietta Street, Suite 3100 Atlanta, GA 30303

Re: McGuire Nuclear Station, Units 1 and 2 IE Bulletin 79-02, Revision 1 Docket Nos. 50-369, 50-370

Dear Mr. O'Reilly:

My letter of August 14, 1979, forwarded to your office a copy of Teledyne Engineering Services Technical Report TR-3501-1. This report contains the results of the cyclic testing which was performed at McGuire per the requirements of the referenced IE Bulletin. In a telephone conversation between Mr. R. B. Priory of Duke Power Company and Mr. W. P. Ang of your office, Duke was informed that a single submittal of this report would be sufficient for replies to this bulletin on all of Duke's nuclear stations. For this reason, my submittal of this report on August 14, 1979, is referenced as Duke's final response to this bulletin for McGuire.

Very truly yours,

William O. Parker, Jr. By 7155

GAC/sch

cc: U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Washington, DC 20555

TE POWER 1904

967 217

7909180567