		ELECO				
TO: Exec	ecutive Director		TO: Director of Regulatory Operation			
Chal	rman. SRC		631 Park Avenue			
Mana	ger of Nuclear Ope	rations	King of Pruss	sia, P	ennsylvania	19406
DATE/TIME	: 8/30/79 -	P.M. DATE	E/TIME: 8/30/7	79 -	P.M.	
FROM:	James A. FitzPatr	rick Nuclear Power	r Plant			
	P.O. Nox 41 Lycoming, New Yor	k 13093				
			SUBJECT:		ET NO. 50-3	LE OCCURRENCE
				LICE	NSE NO. DPR-	-59
				ASSI	GNED OR NO.	79-118
					LER NO.	
EVENT DAT	E: August 30, 19	79	REPORT O	ATE: .	August 30,	1979
EVENT DES	CRIPTION:					
he archit	mately 12:30 p.m. ect-engineer infor	med the staff at	the FitzPatric	k Plan	it that they	concurred
hat the n	resent routing of	the high pressure	coolant injec	tion s	ystem steam	isolation
alve cont	rol cable and the	thermocouple temp	erature detect	cable	separation	iid not
viet hotw	pen these cables a	ind the control ca	bles of the au	toma ti	c depressur	ration
vetom T	his was discovered	during the revie	w of cable sepa	aratio	n for the Ja	mes A.
itzpatric	k fire hazards and trick Plant during	lysis study. Alt	hough not clear	rly a	indicates th	ne separation
ptween th	ose cables should	be increased. We	are therefore	prese	ntly re-rout	ting these
ables to	locations approved	by the architect	-engineer prior	r to s	tartup of th	e FitzPatric
lant.						
CHPONENTS	INVOLVED:					
valve 23-M	DARXOZO, ILKDARXOZ NOV 15 (inside HPC) REMEDIAL ACTION:	1 and IHPIARC103 steam isolation	associated wit	h stea	m leak dete	ction and
	determinate					
emedial Ac	tion - Set forth	above				
ACILITY S				2 TH	ERMAL POWER	N/A
	Routine Startup		Shutdown	X		
	Routine Shutdown			9	-	
	Steady State Power		Hot Appl	icable		
	Load Change		mot appr			
written	follow-up report	vill be sent with	in two weeks.		26	93
					. /	10
				7	1	(1
		1000	46	4	-100	Xd.
	0)[]][][][][]	N	Le V	Mest	CON !
	U	90011:	JOHN D. L			//
		MINIM				EAR PONER PLA
	. (U)(n)	16 INAIS			7.53	N/001
				- 0	a - aak X	711413