

PUBLIC SERVICE COMPANY OF COLORADO

P. O. BOX 840 . DENVER, COLORADO 80201

C. K. MILLEN

August 15, 1979 Fort St. Vrain Unit No. 1 P-79179

Mr. G. L. Madsen, Chief Reactor Operations and Nuclear Support Branch U. S. Nuclear Regulatory Commission Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

Docket No. 50-267

Subject: I & E Inspection Report 79-13

Gentlemen:

This letter is in response to your Notice of Violation (I & E Report 79-13) from your inspection of our facility during the period July 10-13, 1979.

The responses are numbered to correspond with those used in your Notice of Violation.

 (a) All control room operators have been readvised of the need to observe condition of their equipment and to issue PTR's when the equipment becomes inoperable. Those personnel directly involved have received a verbal reprimand for this occurrence.

In addition, Results Department personnel now make daily, Monday to Friday, inspections of all control room recording devices, with special attention to inking and drive mechanisms.

We are now in compliance.

(b) We have determined that the failure to log the required data resulted because the area was inaccessible due to high radiation.

To avoid failing to note reasons for missing data the 12-8 shift supervisor has been assigned the responsibility of reviewing all logs and resolving discrepancies.

We are now in compliance.

249 99076

(continued)

August 15, 1979 P-79179

Mr. G. L. Madsen Page two

> The maintenance personnel involved have been verbally reprimanded for their failure to record their actions properly.

In addition, a newly formed group (plant QC) will, as they gradually assume their duties, conduct inspections of on-going activities and the records thereof.

The consulting firms recommendations (see response to 79-12) are expected to result in more meaningful, easier to use, procedures.

We are now in compliance.

Very truly yours,

PUBLIC SERVICE COMPANY OF COLORADO

C. K. Millen

Senior Vice President

CKM: FMM: i1