

**LICENSEE EVENT REPORT**

**POOR ORIGINAL**

CONTROL BLOCK: 

--	--	--	--	--	--

 ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N E C P R 1 2 0 0 - 0 0 0 0 - 0 0 0 3 4 1 1 1 1 4 5  
7 8 9 14 15 25 26 30 37 CAT 38

CON'T

REPORT SOURCE L 6 0 5 0 0 0 2 9 8 7 0 8 0 9 7 9 8 0 9 0 7 7 9 9

7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 While performing routine surveillance procedure 6.2.1.4.2, MS-DPIS-119B was found with

0 3 a setpoint in excess of that allowed in Technical Specifications Table 3.2.A. All re-

0 4 dundant differential pressure switches were functioning properly and were within spec-

0 5 ification. There were no significant occurrences as a result of this event and there

0 6 were no adverse affects to public health and safety. This event is not repetitive.

0 7

0 8

7 8 9

SYSTEM CODE C D 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE S 15		VALVE SUBCODE Z 16	
7 8		9 10		11 12		13 14		15 16		17 18	
LER/RO REPORT NUMBER 17		EVENT YEAR 7 9 21 22		SEQUENTIAL REPORT NO. 0 2 3 23 24 25 26		OCCURRENCE CODE / 27		REPORT TYPE I 28 29		REVISION NO. 0 30 31 32	
ACTION TAKEN A 18 19		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 23 24 25		ATTACHMENT SUBMITTED N 23 24	
33 34		35 36		37 38		39 40		41 42		43 44	
NPRD-4 FORM SUB. 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER B 0 8 0 26		47		48		49	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 MS-DPIS-119B is a Barton Model 288 differential pressure indicating switch. The cause  
1 1 of the setpoint drift is attributed to a faulty microswitch. The microswitch assembly  
1 2 was replaced.  
1 3  
1 4

8 9  
FACILITY STATUS (28) 10 11 12 13 14  
1 5 9 0 0 0 29 NA 44  
7 8  
ACTIVITY CONTENT  
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)  
1 6 Z (33) Z (34) NA 44  
7 8 9 10 11  
METHOD OF DISCOVERY (31) 45 46 47 48 49 50  
B Surveillance Testing 80  
DISCOVERY DESCRIPTION (32)  
LOCATION OF RELEASE (36)  
NA 80

PERSONNEL EXPOSURES					
NUMBER		TYPE	DESCRIPTION		
1	7	p p	(37) Z	(38)	NA (39)

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	9	11	12	13
				NA	

LOSS OF OR DAMAGE TO FACILITY (43)  
TYPE DESCRIPTION  
1 9 Z (42) NA 7909280 479

PUBLICITY

ISSUED DESCRIPTION

(2) (0) N (44) NA

7 8 9 10 68 69 80

NRC USE ONLY

NAME OF PREPARER David Phillips

PHONE: 402-825-3811