

PRODUCTION DEPARTMENT

Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission Region II - Suite 818 230 Peachtree Street, N. W. Atlanta, Georgia 30303

Attention: Mr. J. P. O'Reilly, Director

Centlemen:

SUBJECT: Grand Gulf Nuclear Station File 0272/L-850.0/L-452.0 Evaluation of IEB - 78-05 *MAEC78/21* REF: RII:JPO 50/416, 50/417 AECM-78/40

Central Le Ce

We have completed our review of IE Bulletin 78-05 entitled "Malfunctioning of Circuit Breaker Auxiliary Contact Mechanism -General Electric Model CR 105X". This mechanism is not utilized on any equipment at the Grand Gulf Nuclear Station. Based on this finding, we are planning no further action in response to this bulletin.

Yours truly,

27 Cale

for J. P. McGaughy, Jr. Director of Power Production

JRF/WDH/LFD:db

cc: Mr. R. C. Travis Mr. T. B. Conner

> U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement Division of Reactor Construction Inspection Washington, D. C. 20555

7910010 8420000

1033 273

Member Middle South Utilities System