

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

September 26, 1979

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - DIESEL GENERATOR FIELD RELAY
COIL (K1) FAILURES - NCR 15P - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
W. T. Cottle on August 27, 1979, in accordance with 10 CFR 50.55(e).
Enclosed is our first interim report. We expect to submit our next
report before fuel loading in unit 1.

If you have any questions concerning this matter, please get in touch
with D. L. Lambert at FTS 854-2581.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stello, Jr., Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

1090 243

Bola
5/11