

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	M	D	C	C	N	1	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
LICENSEE CODE						LICENSE NUMBER						LICENSE TYPE						CAT 58								

01	L	6	0	5	0	0	0	3	1	7	7	0	8	3	1	7	9	8	0	9	2	8	7	9	9	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
REPORT SOURCE		DOCKET NUMBER						EVENT DATE						REPORT DATE												

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 | At 0830 the operator noticed that 1-CC-3830-CV (12 shutdown cooling heat

03 | exchanger outlet valve) was indicating intermediate. Subsequent investigation

04 | revealed that the valve operator had become disconnected from the valve stem

05 | (T.S.3.6:2.1). The valve was repaired and returned to service at 1445. This

06 | is not a repetitive occurrence.

09	W	B	11	E	12	B	13	V	A	L	V	O	P	14	D	15	7	16					
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25					
SYSTEM CODE			CAUSE CODE			CAUSE SUBCODE			COMPONENT CODE						COMP. SUBCODE		VALVE SUBCODE						
17	7	9	21	22	23	0	4	5	24	25	26	27	0	3	28	29	30	31	0	32			
LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.			OCCURRENCE CODE			REPORT TYPE		REVISION NO.											
A	18	A	19	Z	20	Z	21	0	0	0	0	22	N	23	Y	24	A	25	M	1	2	0	26
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT			SHUTDOWN METHOD			HOURS			ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER				

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 | The pivot locking plate failed, disconnecting the actuator (Masoneilan Model

11 | 71-34312) from the valve stem. FCR 79-60 was initiated allowing fabrication

12 | and installation of new plate from stronger material. The actuator was repaired

13 | and returned to service.

15	E	28	1	0	0	29	NA	30	A	31	Operator Observation	32		
7	8	9	10	11	12	13	14	15	16	17	18	19		
FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY				DISCOVERY DESCRIPTION	
16	Z	33	Z	34	NA	35	NA	36	NA	37	NA	38		
ACTIVITY CONTENT			RELEASED OF RELEASE			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
17	0	0	0	37	Z	38	NA	39						
PERSONNEL EXPOSURES			NUMBER			TYPE			DESCRIPTION					
18	0	0	0	40	NA	41	NA	42	1090	389				
PERSONNEL INJURIES			NUMBER			DESCRIPTION								
19	Z	42	NA	43	7910040	316								
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION								
20	N	44	NA	45	S	46								
PUBLCITY ISSUED			DESCRIPTION			NRC USE ONLY								