



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W., SUITE 3100
ATLANTA, GEORGIA 30303

TIC
50-269
270
287

In Reply Refer To:

RII:FJ

50-269/79-18, 50-270/79-16
and 50-287/79-18

SEP 18 1979

Duke Power Company
ATTN: W. O. Parker, Jr.
Vice President, Steam Production
Post Office Box 2178
Charlotte, North Carolina 28242

Gentlemen:

Thank you for your letter of August 31, 1979, informing us of steps you have taken to correct the item of noncompliance concerning activities under NRC Operating License No. DPR-55 brought to your attention in our letter of August 9, 1979. In addition, based on discussions with station management on September 11, 1979, it is our understanding that the deficiencies occurred prior to licensing of the facility and that a program for maintaining drawings up-to-date as a result of changes to the facility exists.

Further, it is our understanding that corrective actions will be initiated for any deficiencies in working file drawings identified on all safety related systems for Oconee Units 1 and 2 prior to the end of the next refueling outage for each respective unit.

We appreciate your cooperation with us.

Sincerely,

R. C. Lewis
R. C. Lewis, Acting Chief
Reactor Operations and Nuclear
Support Branch

cc: J. E. Smith, Station Manager
Post Office Box 1175
Seneca, South Carolina 29678

1108 083

7 910050

290