

July 30, 1979

Mr. J. G. Keppler, Director Directorate of Inspection and Enforcement - Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

> Subject: LaSalle County Station Units 1 and 2 Supplemental Response to IE Inspection Report Nos. 50-373/78-28 and 50-374/78-20 NRC Docket Nos. 50-373 and 50-374

Reference (a): G. Fiorelli letter to B. Lee, Jr. dated February 2, 1979

Dear Mr. Keppler:

In order to resolve the open issue relative to weld repair records which was addressed in Reference (a), General Electric Company issued Nonconformance Report (NCR) LSFW1-2 for the feedwater safe-end weld in question. The resolution of that NCR documents the repair made to the root of that feedwater safe end (150° azimuth). This documentation is available at LaSalle County Station for review by Region III.

Please direct any additional questions you may have in this regard to this office.

Very truly yours,

Louis O. Del Storge

Assistant Vice-President

1127 153

AUG 1 1979

7910050 494