

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

NGT 2 1979

MEMORANDUM FOR: Those on Attached List

FROM: Helen Pappas, Chief, Administrative Branch

SUBJECT: IE INFORMATION NOTICE NO. 79-24

The attached IE Information Notice No. 79-24 titled "Overpressurization Of Containment Of A PWR Plant After A Main Steam Line Break" was sent to the following licensees on October 1, 1979:

American Electric Power Service Corporation Indiana and Michigan Power Company D. C. Cook 1, 2 (50-315, 50-316)

Cincinnati Gas & Electric Company Zimmer (50-358)

Cleveland Electric Illuminating Company Perry 1, 2 (50-440, 50-441)

Commonwealth Edison Company Braidwood 1, 2 (50-456, 50-457) Byron 1, 2 (50-454, 50-455) Dresden 1, 2, 3 (50-10, 50-237, 50-249) La Salle 1, 2 (50-373, 50-374) Quad-Cities 1, 2 (50-254, 50-265) Zion 1, 2 (50-295, 50-304)

Consumers Power Company Big Rock Point (50-155) Midland 1, 2 (50-329, 50-330) Palisades (50-255)

Dairyland Power Cooperative LACBWR (50-409)

Detroit Edison Company Fermi 2 (50-341)

Illinois Power Company Clinton 1, 2 (50-461, 50-462)

1173 108

OCT 2 1979

- 2 -

Those on Attached List

Iowa Electric Light & Power Company Duane Arnold (50-331)

Northern Indiana Public Service Company Bailly (50-367)

Northern States Power Company Monticello (50-263) Prairie Island 1, 2 (50-282, 50-306)

Ohio Edison Company Erie 1, 2 (50-580, 50-581)

Public Service of Indiana Marble Hill 1, 2 (50-546, 50-547)

Toledo Edison Company Davis-Besse 1 (50-346)

Union Electric Company Callaway 1, 2 (50-483, 50-486)

Wisconsin Electric Power Company Point Beach 1, 2 (50-266, 50-301)

Wisconsin Public Service Corporation Kewaunee (50-305)

> Helen Pappas, Chief Administrative Branch

Attachment: IE Information Notice No. 79-24

Pappas/bk

10/1/79

SSINS: 6870 Accession No: 7908220123

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND ENFORCEMENT WASHINGTON, D. C. 20555

October 1, 1979

IE Information Notice No. 79-24

OVERPRESSURIZATION OF CONTAINMENT OF A PWR PLANT AFTER A MAIN STEAM LINE BREAK

Virginia Electric and Power Co. submitted a report dated September 7, 1979 that identified a deficiency in the original analyses of containment pressurization as a result of a steam line break for North Anna Power Station, Units 3 and 4.

Stone and Webster Engineering Corporation performed a reanalyses of containment pressure following a main steam line break and determined that, if the auxiliary feedwater system continued to supply feedwater at runout conditions to the steam generator that had experienced the steam line break, containment design pressure would be exceeded in approximately 10 minutes. The long term blowdown of the water supplied under runout conditions by the auxiliary feedwater system had not been considered in the earlier analyses. The corrective action is now under review by the owner, architect engineer, and NSSS supplier.

This Information Notice is provided as an early notification of a possibly significant matter that is still under review by the NRC staff. It is expected that recipients will review the information for possible applicability to their facilities. No specific action or response is requested at this time. If NRC evaluations so indicate, further licensee actions may be requested or required.

No written response to this Information Notice is required. If you have any questions regarding this matter please contact the Director of the appropriate NRC Regional Office.

Enclosure: List of IE Information Notices Issued in the Last Six Months



IE Information Notice No. 79-24 October 1, 1979

Enclosure Page 1 of 2

LISTING OF IE INFORMATION NOTICES ISSUED IN LAST SIX MONTHS

Information Notice No.	Subject	Date Issued	Issued To
79-10	Nonconforming Pipe Support Struts	4/16/79	All power reactor facilities with a CP
79-11	Lower Reactor Vessel Head Insulation Support Problem	5/7/79	All holders of Reactor OLs and CPs
79-12	Attempted Damage to New Fuel Assemblies	5/11/79	All Fuel Facilities Research Reactors, and Power Reactors with an OL or CP
79-13	Indication of Low Water Level in the Oyster Creek Reactor	5/29/79	All Holders of Reactor OLs and CPs
79-14	NRC Position of Electrical Cable Support Systems	6/11/79	All Power Reactor Facilities with a CP
79-15	Deficient Procedures	6/7/79	All Holders of Reactor OLs and CPs
79-16	Nuclear Incident at Three Mile Island	6/22/79	All Research Reactors and Test Reactors with OLs
79-17	Source Holder Assembly Damage Damage From Misfit Between Assembly and Reactor Upper Grid Plate	6/20/79	All Holders of Reactor OLs and CPs
79-18	Skylab Reentry	7/5/79	All Holders of Reactor OLs
79-19	Pipe Cracks In Stagnant Borated Water Systems At PWR Plants	7/17/79	All Holders of Reactor OLs and CPs

IE Information Notice No. 79-24 October 1, 1979

1.4.4.14

. . .

Enclosure Page 2 of 2

LISTING OF IE INFORMATION NOTICES ISSUED IN 1979

Information Notice No.	Subject	Date Issued	Issued To
79-20	NRC Enforcement Policy NRC Licensed Individuals	8/10/79	All Holders of Reactor OLs and CPs and Production Licensees with Licensed Operators
79-21	Transportation and Commercial Burial of Radioactive Materia		All power and research reactors with OL's
79-22	Qualification of Control Systems	9/14/79	All power reactor facilities with operating licenses and construction permits.
79-23	Emergency Diesel Generator Lube Oil Coolers	9/26/79	All Power facilities holding OLs and CPs

1173 112

Central files

Addressees - Memorandum dated October 2, 1979

4.1.1

IE Files MPA/DTS Central Files Reproduction Unit NRC 20b

. .

• • •