

U. S. NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT

REGION I

Report No. 11000411/79-01

Docket No. 11000411

License No. ISNM-79003 Priority K Category 5

Licensee: Transnuclear, Incorporated

One North Broadway

White Plains, New York 10601

Facility Name: None

Inspection At: Logan International Airport, Boston, Massachusetts; Columbus International Airport, Piketon, Ohio

Inspection Conducted: July 10, 1979

Type of Inspection: Transportation-Import

Inspectors: R. H. Ladun 9-10-79  
R. H. Ladun, Physical Security Inspector date

R. P. Rosano, Physical Security Inspector (Intern)                       
date

J. F. Scheffer, Physical Security Inspector                       
date

J. Schaper, Physical Security Inspector                       
date

Approved by: J. W. Devlin 9/11/79  
J. W. Devlin, Chief, Security and Investigation date  
Section, Safeguards Branch

Inspection Summary:

Inspection on July 10, 1979 (Report No. 11000411/79-01)

Areas Inspected: Announced inspection and surveillance of the security measures afforded an import shipment of SNM. Specific areas included: Pre-shipment planning and notification; examination of shipping containers, tamper-safe seals, and related shipping documents; shipment monitoring during transfers, and while in transit; communications; procedures and instructions to guards and drivers; and radiological survey. The inspection involved 27 inspector hours by 3 Regional based inspectors and an inspector from IE Headquarters.

Results: Of the areas examined, no items of noncompliance were identified.

899 148

7911070 009