

ENCLOSURE

DESCRIPTION OF VIOLATION

Metropolitan Edison Company
Docket Nos. 50-289 and 50-320
License Nos. CPPR-40 and CPPR-66

Certain activities under your license appear to be in noncompliance with AEC regulations as indicated below:

Section 50.55(e)(2) and (3), Part 50, Title 10 Code of Federal Regulations.

Contrary to the above, the fire which occurred on July 28, 1972 within the RP4 nozzle of Unit No. 1 reactor pressure vessel, and which deposited quantities of chloride contaminants in the reactor coolant system, was not reported to the AEC until August 4, 1972. Furthermore, no written report of this reportable deficiency was submitted to the AEC within the 30 day period following the incident.

1566 198

7911110003 ④