

APPENDIX A

NOTICE OF VIOLATION

Metropolitan Edison Company

Docket Nos. 50-289
50-320

Based on the results of an NRC inspection conducted May 30 - June 2, 1978, it appears that one of your activities was not conducted in full compliance with conditions of your NRC Facility License No. DPR-50 as indicated below. This item is a deficiency.

Technical Specification 6.8.3.c states in part: "Temporary Changes to procedures...may be made provided...The change is documented, reviewed by the Plant Operations Review Committee (PORC), and approved by the Unit Superintendent within 7 days of implementation."

Contrary to the above, as of June 1, 1978, a temporary change, implemented May 12, 1978, had not been reviewed by the PORC nor approved by the Unit Superintendent. This change affected the Reactor Protection System operating procedure.

1566 211

7911110015