

UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION I
970 BROAD STREET
NEWARK, NEW JERSEY 07102

September 7, 1972

J. B. Henderson, Chief, Reactor Construction
Branch, Regulatory Operations, HQ

METROPOLITAN EDISON COMPANY
THREE MILE ISLAND UNITS 1 AND 2
RO REPORT NO. 50-289/72-10 and 50-320/72-02

The subject inspection report is forwarded for information.


The issuance of this report was delayed pending a meeting with the corporate management of this facility, which was not scheduled until August 8, 1972 and concluded on August 9, 1972.

This inspection was made to determine if the QA program inadequacies could be related to the implementation deficiencies, particularly in concrete placement.

The QA program deficiencies do not appear to be of such a nature that could result in the deficiencies which have occurred, except for the fact that QC personnel did not appear to be aware of their authorities.

An inspection to determine the adequacy of implementation was conducted on August 14, 1972 and will be forwarded at an early date.

Please note that Sections II, III, and IV were consolidated due to the nature of the items inspected.


E. M. Howard, Chief
Reactor Construction Br., RO:I

Enclosure:
Subject Inspection Report

cc: P. A. Morris, RO
H. D. Thornburg, RO
R. H. Engelken, RO
J. G. Keppler, RO

R. Minogue, RS (3)
R. S. Boyd, L (2)
R. C. DeYoung, L (2)
D. J. Skovholt, L (2)

H. R. Denton, L (2)
RO Files
DR Central Files

1566 249

7911110022 Q