



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

201 645.

April 17, 1972

J. B. Henderson, Chief, Reactor Construction  
Branch, Division of Compliance, HQ

METROPOLITAN EDISON COMPANY  
THREE MILE ISLAND 1 AND 2  
CO REPORT NO. 50-289/72-04 and 50-320/72-01

The subject inspection report is forwarded for information.

This inspection was conducted concurrent with a visit by DRL/DRS  
personnel. The nonconformance item was identified by D. F.  
Sullivan, DRS.

Progress continues on the ring girder repairs. The licensee  
now predicts a total of 1.57% of all reinforcing steel will  
have nick-weld repairs, including shear bars, on this 180° seg-  
ment.

Exploratory work on the South 180° segment had not yet started  
at the time of this inspection.

*E. M. Howard*  
E. M. Howard  
Senior Reactor Inspector

Enclosure:  
Subject Inspection Report

cc: E. G. Case, DRS (3)  
R. S. Boyd, DRL (2)  
R. C. DeYoung, DRL (2)  
D. J. Skovholt, DRI (3)  
H.R. Denton, DRL (2)  
R. H. Engleken, CO  
L. Kornblith, Jr., CO  
J. G. Keppler, CO  
CO Files  
DR Central Files ✓

1566 286

7911110032