

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

DK 10-2-1-10  
JUL 1 1975

Metropolitan Edison Company  
Attention: Mr. R. C. Arnold  
Vice President  
P. O. Box 542  
Reading, Pennsylvania 19603

License Nos. DPR-50  
CPR-66  
Inspection Nos. 50-289/75-08  
50-320/75-04  
Docket Nos. 50-289  
50-320

Reference: Your letter dated June 16, 1975  
In response to our letter dated May 22, 1975


Gentlemen:

We have reviewed the corrective and preventive actions you documented in response to our correspondence.

Upon further review of the subject area, it was determined that the procedures in question were alternately designated as Health Physics Procedure 1670.12 and Radiation Emergency Procedure 1670.12, both designations appearing as part of your Emergency Plans and Procedures. Revision 0 of this procedure was dated and approved on March 6, 1974. Failures to perform required emergency equipment inventories after this date formed the basis of our enforcement action. It also appears at present, that the requirement for performing emergency equipment inventories is included in two separate procedures, the procedure noted above and H.P. 1778 noted in your letter of June 16, 1975.

The corrective actions described in the above referenced letter will be examined during a subsequent inspection of your licensed program.

Sincerely,



Paul R. Nelson, Chief  
Radiological and Environmental  
Protection Branch



1586 076

911110138

Q 7/17

bcc:

IE Chief, FS&EB

IE:HQ (4)

IE Files

Central Mail & Files

Directorate of Licensing (4)

Regulatory Standards (1)

PDR

Local PDR

NSIC

TIC

REG:I Reading Room

ELD

State of Pennsylvania

Miss Mary V. Southard, Chairman, Citizens for a  
Safe Environment

1586 077