UNITED STATES ATOMIC ENERGY COMMISSION DIVISION OF COMPLIANCE

LICENSEE University of Arizons Department of Euclear Ingineering Tucson, Arizons

2. REGIONAL OFFICE

Region V, Division of Compliance U. S. Atomic Energy Commission 2111 Bencroft Way Berkeley, California 94704

LICENSE NUMBER

4. DATE(3) OF INSPECTION

2-756-16

February 16, 1967

- The following activities under your license (identified in Item No. 3 above) appear to be in noncompliance with AEC regulations or license requirements, as indicated.
 - a. Radiation dose rates of greater than 1 mm/hr existed in Room 166 of the Engineering Building, an unrestricted area. This was contrary to the requirements of Paragraph 10 CFR 20.105(b)(2), "Permissible Levels of Radiation in Emrestricted Arees". This metter was corrected during the course of the inspection. (see para : c)
- . On February 14, 1967, 505 millicuries of tritima were disposed in one operation by buriel at Pages Rench. Disposal of this quantity of material is con-turny to the requirements of Paragraph 10 CFR 20.304(a). "Disposal by Eurich in Soil", which limits the total quantity of tritium which may be disposed by burial et any oce time to 250 millicuries

1322 359

Ecoa AEC Compliance Inspector

3/1/67

7911130

COMIES: _ CO REGION _ CO HEADQUARTERS _ LAR HEADQUARTERS