


B-LINE SYSTEMS, INC.  
104 West Monroe Street  
Huntland Illinois 62249 U.S.A.  
618 654 2184 Telex 44-7755

World Headquarters



POOR ORIGINAL

79-156-001

October 22, 1979

Chicago Regional Office  
Nuclear Regulatory Commission  
799 Roosevelt Road, Building 4  
Clon Ellyn, Illinois 60137

Attention: Mr. Gaston Fiorelli

Gentlemen:

This letter is to advise you that corrective action has been taken in regard to the potentially defective parts reported by B-Line Systems, Inc. on September 24, 1979. Mr. Fike of Ernst-Comstock has informed B-Line Systems that none of the parts identified in our letter of September 24, 1979 have been installed in safety related applications at Cleveland Electric Illuminating's Perry Nuclear Power Station.

B-Line Systems has taken the additional precautionary measure of re-calling all parts which were in storage at the Perry Nuclear Power Station to preclude their inadvertent use in safety related areas.

In light of the facts stated above, B-Line Systems, Inc. considers the reported potential defects to be satisfactorily resolved.

Sincerely yours,

B-LINE SYSTEMS, INC.

*Thomas R. Cold, Sr.*  
Thomas R. Cold, Sr.  
President

/mg

1325 357

OCT 25 1979

7911140/20

MANUFACTURERS OF CABLE TRAY AND STRUT SYSTEMS

ATTACHED IS A PART 21 REPORT FROM IE MAIL UNIT - ROOM 359E/W

PART 21 IDENTIFICATION NO. 79-156-001 COMPANY NAME B-Line System

DATE OF LETTER 10/22/79 DOCKET NO. \_\_\_\_\_

DATE DISTRIBUTED 11/1/79 ORIGINAL REPORT  SUPPLEMENTARY

DISTRIBUTION:

REACTOR(R)

FUEL CYCLE &

SAFEGUARDS(S)

MATERIALS(M)

NRR/DOR, DIRECTOR

AD/FFMSI

AD/SG-IE

NRR/DPM DIRECTOR

NMSS/FCMS

AD/ROI

AD/ROI (2)

REGIONS

REGIONS

AD/RCI

IE FILES

NRR/DOR, DIRECTOR

REGIONS

PDR

NMSS/SG SS-881

IE FILES (2)

LPDR

PDR

CENTRAL FILES

CENTRAL FILES-SS-396

LPDR

CENTRAL FILES (CHRON)

CENTRAL FILES(CHRON)  
(016)

TERA

PDR

TERA

IE FILES (2)

LPDR

BOB DENNIG, MPA

CENTRAL FILES 016

TERA

CENTRAL FILES (CHRON)

BOB DENNIG, MPA

CENTRAL FILES - SS-396

BOB DENNIG, MPA

ACTION:

PRELIMINARY EVALUATION OF THE ATTACHED REPORT INDICATES LEAD RESPONSIBILITY FOR FOLLOW-UP AS SHOWN BELOW:

IE

NRR

NMSS

OTHER

RCI  
ROI  
SG  
FFMSI

**POOR ORIGINAL**

1325 358

REV. 3/5/79