

APPENDIX A

NOTICE OF VIOLATION

General Services Administration  
Washington, D.C. 20406  
License No. STC-133

Docket No. 040-00341

Based on the results of an NRC inspection conducted on August 29, 1979, it appears that certain of your activities were not conducted in full compliance with NRC regulations and the conditions of your license as indicated below:

A. Condition 12 of your license requires that licensed material be possessed and used in accordance with statements, representations and procedures contained in certain referenced applications and letters. One of these letters is dated January 27, 1976.

1. Item 2 of this letter requires twice yearly inspections of the depot by the Regional Radiological Officer.

Contrary to this requirement as of August 29, 1979, you have failed to conduct the required inspections of the Curtis Bay Depot during the past year.

2. Item 7 of this letter requires that instrumentation calibrations be performed by the Regional Radiological Officer using material source sets available for this purpose.

Contrary to this requirement, on the date of the inspection, August 29, 1979, a meter was used which had not been calibrated since April 14, 1978 and no source set was available to calibrate this meter.

These are infractions.

- B. 10 CFR 19.12 requires that you instruct all individuals working in your restricted areas, in the applicable provisions of the Commission's regulations and licenses.

Contrary to this requirement, as of the day of the inspection, August 29, 1979, three individuals who were working in your restricted area had not been instructed in the applicable provisions of the regulations and the conditions of your license.

This is an infraction.

1470 254

7912010045