



MAINE YANKEE ATOMIC POWER COMPANY •  
ENGINEERING OFFICE

TURNPIKE ROAD (RT. 9)  
WESTBORO, MASSACHUSETTS 01581  
617-366-9011

October 29, 1979

WYM 79-121

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Attention: Mr. Boyce H. Grier, Director

References: (1) License No. DPR-36 (Docket No. 50-309)  
(2) USNRC Letter to MYAPC dated September 12, 1979  
IE Bulletin No. 79-23

Dear Sir:

Subject: Potential Failure of Emergency Diesel Generator  
Field Exciter Transformer

As required in Reference (2), we are providing the following information:

- Item 1 The circuitry of the diesel generators for Maine Yankee has been examined and it has been determined that no connection exists between the primary windings of the exciter power transformer and the neutral of the generator.
- Item 2 Maine Yankee will perform the sustained full-load operation test on each diesel generator before January 1, 1980. You will be notified of the results upon completion of testing.

We trust that you will find this information satisfactory; however, should you desire additional information, please contact us.

Very truly yours,

MAINE YANKEE ATOMIC POWER COMPANY

*R. H. Groce*

R. H. Groce  
Senior Engineer - Licensing

SFU/jgh

1474 333

7912040 057