

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV

611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

October 29, 1979

In Reply Refer To: Docket No. 50-131/79-01

> Omaha Veterans Administration Hospital ATTN: Mr. T. P. Mullon Hospital Director 4101 Woolworth Avenue Omaha, Nebraska 68105

Gentlemen:


This refers to the inspection conducted by Mr. D. L. Kelley of this office during October 15-16, 1979, of activities authorized by NRC Operating License No. R-57, and to the discussion of the inspection findings held by Mr. Kelley with you and Mr. A. J. Blotcky at the conclusion of the inspection on October 16, 1979.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were identified.

In accordance with Section 2.790 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons it is claimed that the information is proprietary. It should be prepared so that proprietary information identified is contained in a separate part of the document, since the

1551 181



application, excluding this separate part, will also be placed in the Public Document Room. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

g S-Madan, Chief,

Reactor Operations and Nuclear Support Branch

Enclosure:

IE Inspection Report No. 50-131/79-01

1551 182