



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

December 6, 1979

2-129-3

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Licensee Event Reports  
79-087/03L-0 and 79-039/03X-1  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9d, attached is LER 79-087/03L-0 concerning a leak in a socket weld on the LPSI Flow Orifice Valve. Also attached is an update to a previously reported LER (79-039/03X-1).

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:MAS:skm

Attachments

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, D. C. 20555

Mr. W. D. Johnson  
U. S. Nuclear Regulatory Comm.  
P. O. Box 2090  
Russellville, AR 72301

Mr. Norman M. Haller, Director  
Office of Management and  
Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, D. C. 20555

1592 140