



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 356-2345
November 6, 1979

D. L. ASWELL
Vice President-Power Production

LPL 12346
Q-3-A20.03.13
3-A1.01.04

Mr. Karl V. Seyfrit, Director Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford 3 SES
Docket No. 50-382 - IE Bulletin 79-23

Dear Mr. Seyfrit:

We have reviewed the subject bulletin and have determined that the generator and excitation transformer do not have a common neutral. The excitation transformer neutral is allowed to float with respect to the generator neutral.

LP&L will conduct the testing required by this bulletin prior to Hot Functional Testing.

If you have any questions, please advise.

Yours very truly,

D. L. Aswell

DLA/JFK/ddc

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operation Inspection
Washington, D. C. 20555

1592 37

7912170 357

Q