LICENSEE EVENT REPORT

	EIGENGEE EVENT HEI ONT
	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1	C O F S V 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 2 0 4 57 CAT 58 5
	REPORT L 6 0 5 0 0 0 2 6 7 7 1 0 2 9 7 9 8 1 2 1 0 7 9 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 Standby diesel engine 1B tripped on high cooling water temperature during surveillance
0 3	test because cooling water valves were lined up incorrectly. Reportable per Fort St.
0 4	Vrain Technical Specification AC 7.5.2(b)3. No accompanying occurrence. Cooler
0 5	isolated, bypass not opened. No affect on public health or safety. Redundant diesel
0 6	engine available and operable.
0 7	
7 8	9 SYSTEM CAUSE CAUSE COMP. VALVE
0 9	W A 10 A 12 B 13 V A L V E X 14 E 15 D 16
	SEQUENTIAL REPORT NO. LER/RO EVENT YEAR 17 9
	ACTION FUTURE EFFECT SHUTDOWN HOURS 22 ATTACHMENT PRIME COMP. COMPONENT MANUFACTURER SUBMITTED FORM SUB. SUPPLIER SUPPLIER SUBMITTED FORM SUB. SUPPLIER SUPP
10	Standby diesel engine 1B cooler isolated to repair cooling water tube leak. Clear-
11	ance point form specified opening cooler bypass valve. Valve was not opened as re-
1 2	quired. Operator reinstructed. Cooling water restored. Surveillance test com-
1 3	pleted.
1 4	
7 8	9 FACILITY STATUS S POWER OTHER STATUS OT
	ACTIVITY CONTENT ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) N/A MOUNT OF ACTIVITY (35) N/A N/A N/A
1 7	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 0 0 0 37 Z 38 N/A
18	PERSONNEL INJURIES NUMBER DESCRIPTION 41 0 0 0 40 N/A
1 9	Loss of or Damage to Facility (3) TYPE DESCRIPTION Z (42) N/A 79/2/806/0
7 8	PUBLICITY ISSUED DESCRIPTION 45 NAC USE ONLY NAC USE ONLY
7 8	9 10 NAME OF PREPARER JAMES J. W. Gahm PHONE: 68 69 (303) 785-2253