

TIC

DAIRYLAND POWER COOPERATIVE

La Crosse, Wisconsin

54601

November 30, 1979

In reply, please refer to LAC-6666

DOCKET NO. 50-409

Mr. James G. Keppler
Regional Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
IE BULLETIN NO. 79-25 - FAILURES OF WESTINGHOUSE
BFD RELAYS IN SAFETY-RELATED SYSTEMS

Reference: 1) NRC Letter, Keppler to Linder,
dated November 2, 1979.

Dear Mr. Keppler:


In response to IE Bulletin No. 79-25 contained in Reference 1,
we have determined the following:

- 1) Westinghouse Type BFD/NBFD Relays are not used or planned to be used in safety or non-safety related systems at our facility.

If there are any questions concerning this response, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE



Frank Linder, General Manager

FL:WRN:af

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operation Inspection
Washington, D. C. 20555

1635 357

DEC 10 1979

7 912210 174