

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76012

October 4, 1979

License No. 49-16194-02

Northwest Community College Northwest Analytical Laboratory 733 Beckman Street Powell, Wyoming 82435

Gentlemen:


This refers to the inspection conducted by Ms. Jean Dawson of this office on September 5, 1979, of the activities authorized by NRC Byproduct Material License No. 49-16194-02 and to the discussion of our findings held by Ms. Dawson with Dr. S. Orendorff and Mr. M. Sanders on September 5, 1979.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, and observations by the inspector.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NC requirements, as set forth in the Notice of Violation, enclosed herewith. This item of noncompliance has been categorized into the level as described to you during the inspection on September 5, 1979.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective actions which have been taken by you and the results achieved; (2) corrective actions which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved.

2180 177



Northwest Community College Northwest Analytical Laboratory -2-

Should you have any questions concerning this letter, please let me know.

Sincerely,

R.S. Excelt for Glen D. Brown, Chief

Glen D. Brown, Chief Fuel Facility and Material Safety Branch

Enclosure: Notice of Violation

and the second

2180 178