

UNITED STATES NUCLEAR REGULATORY COMMISSION **REGION I** 631 PARK AVENUE KING OF PRUSSIA, PENNSYLVANIA 19406

Docket No. 30-4484

OCT 2 9 1979

Raytheon Company The Machlett Laboratories Inc. ATTN: Herman A. Vahjen General Manager 70 Ryan Street Stamford, Connecticut 06907

Gentlemen:

Subject: Inspection No. 30-4484/79-01

This refers to the inspection conducted by Mr. Stearns of this office on October 10, 1979, of activities authorized by NRC License No. 6-18105-01 and to the discussions of our findings held by Mr. Stearns with yourself and Dr. Metal of your staff at the conclusion of the inspection.

The inspection was an examination of activities conducted urder your license as they relate to radiation safety and to compliance with the commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed.

From the discussions conducted during the inspection, it is our understanding that you will test all of your sealed sources for leakage at intervals not to exceed six months and will use tongs when handling these sources. We will review this matter during the next inspection of your licensed program.

In accordance with Section 2.790 of the NRC's "Rules of Practice." Part 2. Title 10, Code of Federal Regulations, a copy of this letter will be placed in the Public Document Room.

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely.

Robert O. McClintock, Chief Materials Radiological Protection Section

8001040 455

2181 275

TERA