



PUBLIC SERVICE COMPANY

PHOENIX, ARIZONA 85036 P. O. BOX 21666

> November 30, 1979 ANPP-14351 - JMA/JPS

MODEL WINGSTERN MINE PROPERTY OF THE PROPERTY

Secretary of the Commission U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Attention: Docketing and Service Branch

Subject:

Regulatory Guide comments on LWR Core Reloads; Guidance on Applications for Amendments to Operating Licenses and on Refueling and Startup Tests SC-521-4

File: 79-010-026

Dear Sirs:

Arizona Public Service Company has reviewed the subject Regulatory Guide. Our comments are attached.

Very truly yours,

EEVin Bount Jo Jan aufor E. E. Van Brunt, Jr. APS Vice President,

Nuclear Projects ANPP Project Director

EEVBJr/JPS/av Attachment

1756 352

Acknowledged by card....

Comments

Page 10, Section 2.3.3:

The requirements of the section should be modified to permit the use of expected burnup parameters for the subject reload core, as burnup history applicable to a particular core may be limited or non-existent. This modification will also allow more timely completion of any necessary analyses required for the reload application.

Page 16, Section 4.1:

The requirements of this section concerning photographic verification are overly restrictive. Sufficient assurance can be provided through verification of assembly placements depicted on a hard copy core loading map.

Page 17, Section 4.3, Subsections a. and b.:

Descriptions of these programs should be required only if they (1) deviate from the approved programs described in the FSAR or (2) are directly related to either technical specification changes or an unresolved safety question.

Page 17, Section 4.3, Subsection c.:

A post irradiation surveillance program of spent fuel should be initiated only upon definitive indication of fuel failure in excess of normally expected levels.

1756 353