



REFINERY PRODUCTS CORP.

MILWAUKEE, WISCONSIN

STANDARDS & SPECIAL FURNACE FITTINGS
FOR REFINERIES & PETRO-CHEMICAL PLANTS
TUBE SUPPORTS - LOW ALLOY AND
STAINLESS STEEL CASTINGS

REPLY TO:
870 WISCONSIN COMMERCE DRIVE
P. O. BOX 278
MENOMONEE FALLS, WIS. 53051
Telephone:
(414) 255-2390

February 4, 1981

U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glenn Ellyn, IL 60317

Attention: W. L. Davis
Acting Chief
Fuel Facility and Materials Safety Branch

Subject: Our License No. 48-03665-02

Gentlemen:

Pursuant to your letter of January 16, 1981, and per 10CFR 20.401 which requires each licensee to maintain records showing results of survey required by 20.205, as noted we failed to record the results of our package survey when we received our incoming IR-192 source from Automation Industries. Our operating procedure clearly states this should be done. Through our error we failed to record this information. This has been brought to the attention of all of our radiographic personnel, and this error will not occur again.

I trust that this corrective action will bring our Radiographic operations in complete compliance with the Nuclear Regulatory Commission's regulations.

If there are any further comments, or questions, that you may have, please do not hesitate to contact writer.

Very truly yours,

REFINERY PRODUCTS CORP.

Leo J. Warden
Radiation Safety Officer

LJW/th
cc

2103110 499

FEB 05 1981



REFINERY PRODUCTS CORP.

MILWAUKEE, WISCONSIN

REPLY TO:
1190 W14555 COMMERCE DRIVE
P.O. BOX 278
MENOMONIE FALLS, WIS. 53051
Telephone:
(414) 233-2490

POOR ORIGINAL

February 4, 1981

U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glenn Ellyn, IL 60317

Attention: W. L. Davis
Acting Chief
Fuel Facility and Materials Safety Branch

Subject: Our License No. 48-03665-02

Gentlemen:

Pursuant to your letter of January 16, 1981, and per 10CFR 20.401 which requires each licensee to maintain records showing results of survey required by 20.205, as noted we failed to record the results of our package survey when we received our incoming IR-192 source from Automation Industries. Our operating procedure clearly states this should be done. Through our error we failed to record this information. This has been brought to the attention of all of our radiographic personnel, and this error will not occur again.

I trust that this corrective action will bring our Radiographic operations in complete compliance with the Nuclear Regulatory Commission's regulations.

If there are any further comments, or questions, that you may have, please do not hesitate to contact writer.


Very truly yours,

REFINERY PRODUCTS CORP.

Leo J. Warden
Radiation Safety Officer

LJW/th
cc

"I affirm the above statements are true" 2-13-81


Leo J. Warden
Radiation Safety Officer

FEB 18 1981