

Note to: H. Denton

From: D. Ross, Jr.

Subject: ST. LUCIE

St. Lucie is ready to restart from refueling Monday, May 28. Problems exist:

1. Exams for new operators recently given (routine, not TMI) indicate less than 50% qualified (7 of 12 fail).
2. We understand that there is a shortage of licensed operators to the point of some overtime is involved (we do not know how much).
3. If we add an additional operator to manipulate AFW then either:
 - a. they must designate a utility operator and train him;
 - b. they must further extend the existing LO.
4. The results from this test indicate a need to audit capabilities of existing LO. OLB, however, is severely stretched on many other fronts.
5. Apparently FPL management is not paying enough attention to training, else they would not have certified these 12 new people as safe and competent operators.
6. We probably could license at this time at least two of the 12 examinees; the other 3 will need further review by P. Collins.

c. extra op
transient Fw
op

D. F. Ross, Jr.

4 in CR

① SS SLO }

② 2 RO }

③ 1 watch foreman (SLO, RO)
1 over

7907020188

268 098

ROISMAN 79-98

P, A

POWER PLANT EXAMINATION RESULTS SUMMARY SHEET

1. FACILITY ST. Lucie

DATE OF WRITTENS 4/2-4/3-79

DATE OF ORALS 4/3-46-79

CHIEF EXAMINER B. Wilson

TYPE OF EXAM (COLD) (HOT)

Simulator Certified

E	A	B	C	D	E	F	G	TOTAL	H	I	J	K	L	TOTAL ORAL	DENT CODE
87	75	75	46	85	63	74	72.0								F
96	96	86	91	89	79	99	90.5								P
89	90	94	84	70	87	85	85.9								P
73	87	70	42	80	65	93	72.1								F
94	82	64	64	30	73	90	70								F
100	89	63	61	68	82	89	78.3								P
84	83	61	82	60	71	93	75.7								F
69	85	67	73	62	95	92	77.5								P
73	80	60	83	61	77	86	74.1								P
80	96	76	43	76	90	84	78.0								F
61	86	67	62	71	74	64	69.9								F
61	96	68	48	52	85	63	68.1								F

POOR ORIGINAL

268 099