BUISDER'S'BEESARS'S' EDSTON BUSSESS



P.O. BOX 270 HARTFORD, CONNECTICUT 06101 (203) 566-6911

July 9, 1979 MP-2-4072

Mr. Boyce H rier Director, Region I Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 631 Park Avenue King of Prussia, Pennsylvania 19406

Reference: Facility Operating License No. DPR-65

Docket No. 50-336

Reportable Occurrence RO-50-336/79-15/3L-0

Dear Mr. Grier:

This letter forwards Licensee Event Report 79-15/3L-0 required to be submitted within thirty days pursuant to Millstone Unit 2 Appendix A Technical Specifications, Section 6.9.1.9.b, conditions leading to operation in a degraded mode permitted by a limiting condition for operation. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY CO.

J. F. Opeka

Station Superintendent

JFO/RAS:mw

Attachment: LER 79-15/3L-0

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (30) Director, Office of Management Information and Program Control,

Washington, D.C. (3)

353 054

