

TIC

PHILADELPHIA ELECTRIC COMPANY

2301 MARKET STREET

P.O. BOX 8699

PHILADELPHIA, PA. 19101

(215) 841-5001

SHIELDS L. DALTROFF  
VICE PRESIDENT  
ELECTRIC PRODUCTION

June 6, 1979

Re: Docket Nos.: 50-277  
50-278

IE Bulletin 79-03

Mr. Boyce H. Grier, Director  
Office of Inspection & Enforcement  
Region I  
United States Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406


Dear Mr. Grier:

This letter is our complete response to IE Bulletin No. 79-03, forwarded to us on March 12, 1979, concerning longitudinal weld defects in ASME SA-312 type 304 stainless steel pipe spools manufactured by Youngstown Welding and Engineering Company.

We have completed our review of the pertinent records and have determined that no pipe spools manufactured by Youngstown Welding and Engineering Company are installed in safety related systems at Peach Bottom Atomic Power Station.

Should you have any questions or require additional information, please do not hesitate to contact us.

Very truly yours,



cc: United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Construction Inspection  
Washington, DC 20555

346 346

7507190080