

POWER & LIGHT / P. D. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

July 6, 1979

D. L. ASWELL Vice President-Power Production

LPL 11489 Q-3-A35.07

Mr. K.V. Seyfrit, Director, Region IV U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3 Docket No. 50-382

Potential Incident No. 21

Rosemount 1153 Series A Pressure Transmitters

Dear Mr. Seyfrit:

This is to confirm the telecon on June 29, 1979 between your Mr. R.C. Stewart and our Mr. T.F. Gerrets. In accordance with the requirements of 10CFR50.55(e), LP&L is continuing to evaluate the reportability of the problem with the Rosemount 1153 Series A Pressure Transmitters. This problem was previously reported to Mr. Stewart by telecon on June 1, 1979. We expect to complete our evaluation by July 31, 1979 and will notify you of the results of our evaluation by that date.

Yours very truly,

Cours

D.L. Aswell

DLA/TFG/ys

cc: Ebasco (2), J.M. Brooks, J. Crnich (2), D.L. Aswell, L.V. Maurin, D.B. Lester, F.J. Drummond, T.F. Gerrets, C.J. Decareaux, S.A. Alleman, T.K. Armington, P.V. Prasankumar, Waterford 3 Staff (2), D.C. Gibbs, L. Biondolillo, R. Hymes

7907260021

413