

APPENDIX A  
NOTICE OF VIOLATION

Pittsburgh Testing Laboratory  
Pittsburgh, Pennsylvania 15220  
License No. 37-00276-25

Docket No. 37-00276-25

Based on the results of an NRC inspection conducted on September 25, 1980, it appears that one of your activities was not conducted in full compliance with the conditions of your license as indicated below:

Condition 10 of your license limits storage of byproduct material to certain named places.

Contrary to this requirement, as of September 25, 1980, a Troxler gauge containing byproduct material was routinely stored at 4920 Cone Road, NW., Roanoke, Virginia 24019, a location not so named.

This is an infraction.

8104140338