

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

611 PYAN PLAZA DRIVE, SUITE 1000 ARLINGTON, TEXAS 76011

APR 0 3 1981

License No. 35-19071-01

Precision Perforators, Inc. ATTN: Mike Reeder, President 6800-B Melrose Lane Oklahoma City, OK 73120

Gentlemen:



Thank you for your letters of March 4 and 18, 1981, in response to our letters dated February 20 and March 13, 1981, and the attached Notice of Violation. We have no further questions at this time, and we will review your corrective action during a future inspection.

Sincerely,

Glen D. Brown, Chief

Technical Inspection Branch