



PRECISION PERFORATORS  
INCORPORATED

March 18, 1981

License # 35-19071-01

U. S. Nuclear Regulatory Commission  
Attn: Mr. Glen Brown  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Gentlemen:

In reference to the letter we received on Feb. 26, 1981 concerning the safety inspection conducted on Feb. 6, 1981 and the notice of Violations attached to that letter. Also the telephone conversation on March 11, 1981 concerning additional information to the corrective steps taken to avoid further violations.

On Feb. 18, 1981, we sent a letter requesting an increase from 50 Millicuries to 100 Millicuries of Iridium and Iodine to be added to our license. In the future, records will be kept up to date and observed by Mr. Mike Reeder to ensure the correct amount of each does not exceed the regulations of our license.

As of Feb. 9, 1981, surveys have been taken on a monthly basis by Mr. Mike Reeder using a Victoreen type meter which was calibrated on Nov. 11, 1980. In the future our records will be kept up to date and reviewed by Mr. Mike Reeder and committee on a regular basis.

Leak tests were taken and sent in to Gulf Nuclear on Feb. 11, 1981; we received the negative results on March 7, 1981. A leak test file has been established and will be reviewed monthly by Mr. Mike Reeder. All Sources will be tested and sent in on proper dates.

If additional information is required, please let us know.

Sincerely,

Mike Reeder  
President

Precision Perforators, Inc.

MR/br

8104170214

MY Comm. Expires 3-2-1983

Subscribed and Sworn to before me  
this 10 Day of March, 1981