



Metropolitan Edison Company
Post Office Box 542
Reading Pennsylvania 19640
215 929-3601

Writer's Direct Dial Number

July 6, 1979
GQL 0875

Mr. B. H. Grier, Director
Region I
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
King of Prussia, PA 19406


Dear Sir:

Three Mile Island Nuclear Station, Unit 1 (TMI-1)
Operating License No. DPR-50
Docket No. 50-289
LER 79-12/01T-0

Attached please find the subject event report, which concerns the failure of an Engineered Safeguards Actuation System relay to "drop out" when de-energized. Although the individual relay failure is not otherwise reportable, this event is being reported per TMI-1 Technical Specification 6.9.2.A(9) as a potentially generic problem.

This report is submitted late per the July 3, 1979 telecon between our Mr. W. S. Stanley and your Mr. D. Johnson.

Sincerely,



J. G. Herbein
Vice President
Generation

JGH:WSS:mrm
Attachments

347 122

A002
5/11
③