

EMAIL

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

500C Chestnut Street Tower II

June 21, 1979

25:52

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

SEQUOYAH NUCLEAR PLANT UNITS 1 AND 2 - PIPE SUPPORT DESIGNERS DID NOT
IN SOME CASES CONSIDER THE SUM OF DEFLECTIONS DUE TO THERMAL, STATIC,
AND SAFE SHUTDOWN EARTHQUAKE - NCR SWP-79-S-7 - FIRST INTERIM REPORT

The subject deficiency was initially reported to NRC-OIE Inspector
Bill Cottle on May 22, 1979, in accordance with 10 CFR 50.55(e).
Enclosed is our first interim report. We expect to submit our next
report by September 10, 1979.

If you have any questions concerning this matter, please get in
touch with D. L. Lambert at FTS 854-2581

Very truly yours, .

J. E. Gilleland

J. E. Gilleland
Assistant Manager of Power

Enclosure

cc: Mr. John G. Davis, Acting Director (Enclosure)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

POOR ORIGINAL

13019
S 1/1

337 216

③

354

S

7907090

740346
d/ter 369. TICAL COP