


PGE



Portland General Electric Company
Trojan Nuclear Plant
P.O. Box 439
Rainier, Oregon 97048

July 5, 1979
BDW-620-79

Mr. R. H. Engelken, Director
Nuclear Regulatory Commission, Region V
1990 North California Blvd.
Walnut Creek, California 94596

Dear Sir:

In accordance with the Trojan Plant Operating License, Appendix A, US NRC Technical Specifications, Paragraph 6.8.1.9, attached is Licensee Event Report No. 79-11. This report is a followup to PGE letter BDW-575-79 dated July 26, 1979 notifying you of a condition when in the event of a high energy line break inside containment, the indicated steam generator water level could be higher than the actual level. In the specific case of a feedwater line rupture inside containment, the primary signal would be delayed.

Sincerely,

B. D. Withers
Plant Superintendent

JCP

BDW/JCP:ga

Attachments

c: LER Distribution

(4)

7907110 422

over 425

478
~~478~~ 161
A002
5 1/1