

USNRC REGION II  
ATLANTA, GEORGIA

79 MAY 25 AIO: 42



May 4, 1979

PRN-AD-79-50  
File 920TP

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 310G  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: Turkey Point Units 3 & 4  
Docket Nos. 50-250 and 50-251  
I&E Bulletin 79-06A

This letter confirms our telephone conversation on May 2, 1979 during which I agreed that Turkey Point would establish procedures and instructions to the operators that in the event of HPI initiation with RCP's operating at least two RCP's will remain operating as long as the pumps are providing forced flow.

This agreement is contrary to our response to item 7C of I&F Bulletin 79-06A. However, we are continuing to work with our NSSS vendor to determine the proper disposition of this item.

Very truly yours,

*for* *J.R. Bensen*  
A. D. Schmidt  
Vice President  
Power Resources

GEL/cph

305 071

790711 0722

OFFICIAL COPY

PEOPLE SERVING PEOPLE