



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76011

RDR: 1109

February 27, 1979

License No. 35-17596-01

Lawton Wastewater
Treatment Plant
ATTN: Mr. Bill McIntyre
Route 2, Box 69
Lawton, Oklahoma 73501

Gentlemen:

This refers to the inspection conducted by Mr. Mustain of this office on February 9, 1979, of the activities authorized by NRC Byproduct Material License No. 35-17596-01 and to the discussion of our findings held by Mr. Mustain with Mr. McIntyre on February 9, 1979.

The inspection was an examination of the activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations, and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements and observations by the inspector.

Based on the results of this inspection, it appears that one of your activities was not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith. This item of noncompliance has been categorized into the level as described in the correspondence to you dated December 31, 1974.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office, within twenty (20) days of your receipt of this notice, a written statement or explanation in reply including: (1) corrective actions which have been taken by you and the results achieved; (2) corrective actions which will be taken to avoid further items of noncompliance; and (3) the date when full compliance will be achieved.

457 218

9

7967250047


Lawton Wastewater
Treatment Plant

-2-

February 27, 1979

Should you have any questions concerning this letter, please let me know.

Sincerely,



Glen D. Brown, Chief
Fuel Facility and Material
Safety Branch

Enclosure:
Notice of Violation

457 219