

License No. 35-17596-01

Notice of Violation

Based on the results of the NRC inspection conducted on February 9, 1979, certain activities appear to be in noncompliance with NRC regulations as indicated below:

Contrary to 10 CFR 31.5(c)(2), the nominal 50 millicurie cesium-137 source Kay Ray Model 7062, used to measure flow on a conveyor belt, was not always tested for leakage at intervals not to exceed six months during the period June 30, 1977, to February 9, 1979.

This is an infraction.

7907250 2205
451