



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76012

June 15, 1979


License No. 35-17596-01

Lawton Wastewater  
Treatment Plant  
ATTN: Mr. Bill McIntyre  
Route 2, Box 69  
Lawton, Oklahoma 73501

Gentlemen:

Thank you for your letters of March 19, April 23, and May 17, 1979, in response to our letters dated February 27, April 9, and May 4, 1979. As a result of Mr. Mustain's discussion with Mr. McIntyre on June 13, 1979, we understand that: (1) the required leak test was performed on May 23, 1979; (2) records of leak test results are being maintained in Mr. McIntyre's office, and (3) an in-office suspense file has been created to assure that future leak tests are performed at intervals not to exceed six months. Therefore, we have no further questions at this time and will review your corrective action during a future inspection.

Sincerely,

  
Glen D. Brown, Chief  
Fuel Facility and Material  
Safety Branch

457 256

7907250 285