LICENSEE EVENT REPORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 V A N A S 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 1 4 5 6 5 1 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6
REPORT LG 0 5 0 0 0 3 3 8 7 0 6 2 8 7 9 8 0 7 2 6 7 0 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 O 2 On June 28, 1979, the 7 day surveillance of the emergency diesel generator batteries
[0]3 [exceeded the surveillance interval +25%. This event is reportable pursuant to
[0]4] [T.S. 6.9.1.9.c. The health and safety of the general public were not affected by
o 5 this occurrence.
06
07
7 8 9
SYSTEM CODE CODE SUBCODE SUBCO
17 REPORT 7 9
[1] [Ammendment No. 11 to License No. NPF-4 dated 6/14/79 added surveillance requirement
[1] [4.8.1.1.3.a to the Technical Specifications. This change was received at North
Anna Power Station on 6/26/79, thereby exceeding the first surveillance interval
+25%. The periodic test (1-PT-85) was revised to incorporate the change and the test
was performed satisfactory.
1 5 E 28 0 9 9 9 NA 2 13 10 12 13 13 14 45 46 18 10 12 13 10 12 13 10 12 13 10 12 13 10 10 10 10 10 10 10
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 NA
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 NA 1 7 0 0 0 37 Z 38 NA
PERSONNEL INJURIES NUMBER DESCRIPTION 41 NA NA
1 9 LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA 7 907310436 7 907310436
PUBLICITY ISSUED DESCRIPTION 45 NA NA NA NA NA NA
7 8 9 10 68 69 80-5
NAME OF PRICARER W. K. Cartwright PHONE: 703-894-5151

Virginia Electric and Power Company North Anna Power Station, Unit #1 Docket No. 50-338 Report No. LER 79-086/03L-0

Attachment: Page 1 of 1

Description of Event

On June 28, 1979 during normal power operations, the weekly surveillance of the diesel generator batteries exceeded the surveillance interval (7 days) +25%

Probable Consequences of Event

Periodic test 1-PT-85, excluding the new requirement, was performed within it's required time frame. Therefore, the health and safety of the general public were never affected by this event. Since Unit 2 is not yet operational, this occurrence is not applicable.

Cause

Ammendment No. 11 to License No. NPF-4 dated June 14, 1979, added surveillance requirement 4.8.1.1.3.a to the Technical Specifications. This amendment was received by North Anna Power Station twelve days later on June 26, 1979, thereby exceeding the first surveillance interval (7 days) +25%.

Immediate Corrective Action

Periodic test 1-PT-85 was revised to incorporate the new requirement and the test was performed satisfactory.

Scheduled Corrective Action

No scheduled corrective action required.

Actions Taken to Prevent Recurrence

No further action required.