



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

CENTRAL FILES
~~FOR:HQ~~
TIC
NSIC


July 6, 1979

In Reply Refer To:
Docket No. 50-131

Omaha Veterans Administration Hospital
ATTN: Mr. T. P. Mullon
Hospital Director
4101 Woolworth Avenue
Omaha, Nebraska 68105

Gentlemen:

This IE Information Notice is provided as an early notification of a possibly significant matter. It is expected that recipients will review the information for possible applicability to their facilities. No specific action or response is requested at this time. If you have questions regarding this matter, please contact the Director of the appropriate NRC Regional Office.


Karl V. Seyfrit
Director

Enclosures:

1. IE Information Notice
No. 79-18
2. List of IE Information Notice
Issued in 1979

~~500280~~

646 005

~~790731~~

7907310615

UNITED STATES
NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT
WASHINGTON, D.C. 20535

IE Information Notice No. 79-18
Date: July 6, 1979
Page 1 of 1

SKYLAB REENTRY

Description of Circumstances:

The most recent dates for reentry of Skylab are July 10 to 14, 1979, with July 12, as the most probable date. Recognizing that a hit on a nuclear reactor would be highly unlikely by Skylab debris, the NRC believes it would be prudent for licensees to review their contingency plans in case such an event should actually occur.

The NRC is in communication with the Department of Energy (DOE), and will receive notification from them as soon as the reentry corridor can be established. This notification may occur within 1 to 2 hours before reentry actually occurs. If it is determined that there are any licensed nuclear power plants in the reentry corridor, the plants will receive notification from their respective Regional Office via the dedicated phone line.

This Information Notice is provided as an early notification of a possibly significant matter. It is expected that recipients will review the information for possible applicability to their facilities. No specific action or response is requested at this time. If further NRC evaluations so indicate, an IE Circular or Bulletin will be issued to recommend or request specific licensee actions. If you have questions regarding the matter, please contact the Director of the appropriate NRC Regional Office.

No written response to this information notice is required.

646 006

79-120387

LISTING OF IE INFORMATION NOTICES
ISSUED IN 1979

Information Notice No.	Subject	Date Issued	Issued To
79-01	Bergen-Paterson Hydraulic Shock and Sway Arrestor	2/2/79	All power reactor facilities with an Operating License (OL) or a Construction Permit (CP)
79-02	Attempted Extortion - Low Enriched Uranium	2/2/79	All Fuel Facilities
79-03	Limitorque Valve Geared Limit Switch Lubricant	2/9/79	All power reactor facilities with an Operating License (OL) or a Construction Permit (CP)
79-04	Degradation of Engineered Safety Features	2/16/79	All power reactor facilities with an Operating License (OL) or a Construction Permit (CP)
79-05	Use of Improper Materials In Safety-Related Components	3/21/79	All power reactor facilities with an Operating License (OL) or a Construction Permit (CP)
79-06	Stress Analysis of Safety-Related Piping	3/23/79	All Holders of an Reactor Operating License (OL) or a Construction Permit (CP)
79-07	Rupture of Radwaste Tanks	3/26/79	All power reactor facilities with an Operating License (OL) or a Construction Permit (CP)

79-08	Interconnection of Contaminated Systems with Service Air Systems Used As the Source of Breathing Air	3/28/79	All power reactor facilities with an Operating License (OL) and Pu Processing fuel facilities
79-09	Spill of Radioactively Contaminated Resin	3/30/79	All power reactor facilities with an Operating License (OL)
79-10	Nonconforming Pipe Support Struts	4/16/79	All power reactor facilities with a Construction Permit (CP)
79-11	Lower Reactor Vessel Head Insulation Support Problem	5/7/79	All Holders of Reactor Operating Licenses (OLs) Construction Permits (CPs)
79-12	Attempted Damage to New Fuel Assemblies	5/11/79	All fuel facilities, research reactors, and power reactors with an Operating Licensee (OL) or a Construction Permit (CP)
79-13	Indication of Low Water Level in the Oyster Creek Reactor	5/29/79	All Holders of Operating License (OL) or Construction Permit (CP)
79-14	NRC Position of Electrical Cable Support Systems	6/11/79	All Power Reactor facilities with a Construction Permit (CP) and applicants
79-15	Deficient Procedures	6/7/79	All Holders of Reactor Operating Licenses (OLs) and Construction Permits (CPs)
79-16	Nuclear Incident at Three Mile Island	6/22/79	All Research Reactors and Test Reactors with Operating Licenses (OLs)
79-17	Source Holder Assembly Damage From Misfit Between Assembly and Reactor Upper Grid Plate	6/20/79	All Holders of Reactor Operating Licenses (OLs) and Construction Permits (CPs)

Mr. John Tillinaghast
Indiana and Michigan Electric Company
Indiana and Michigan Power Company

- 2 - May 15, 1979

cc: Mr. Robert W. Jurgensen
Chief Nuclear Engineer
American Electric Power
Service Corporation
2 Broadway
New York, New York 10004

Gerald Charnoff, Esquire
Shaw, Pittman, Potts and Trowbridge
1800 M Street, N.W.
Washington, D. C. 20036

David Dinsmore Comey
Executive Director
Citizens for a Better Environment
59 East Van Buren Street
Chicago, Illinois 60605

Maude Reston Palenske Memorial
Library
500 Market Street
St. Joseph, Michigan 49085

Mr. D. Shaller, Plant Manager
Donald C. Cook Nuclear Plant
P. O. Box 458
Bridgman, Michigan 49106

Kenneth R. Baker
2874 Robin Hood Drive
Stevensville, Michigan 49127

646 009