

SEABROOK STATION Engineering Office: 20 Turnpike Road Westborough, MA 01581

July 12, 1979

SB-8012 T.F. B 4.2.5

United States Nuclear Regulatory Commission Region I 631 Park Avenue King of Prussia, Pennsylvania 19406

Attention: Office of Inspection and Enforcement

Reference: 1. Docket No. 50-443 and 50-444

2. NRC letter dated May 22, 1979

3. IE Bulletin 79-11

Subject: Faulty Overcurrent Trip Device in Circuit Breakers for

Engineered Safety Systems

Dear Sir:

We have reviewed the referenced IE Bul'atin 79-11 and have determined that we are not using this device in any safety related service in the Seabrook design.

Very truly yours,

David a Marchand

John DeVincentis And Project Manager

DAM: tla

cc: B.B. Beckley

J.H. Herrin

W.E. Wright

522 264

7808070 705 0