



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
611 RYAN PLAZA DRIVE, SUITE 1000  
ARLINGTON, TEXAS 76012

22 MAY 1979

Docket No. 99900021/79-01

Pullman Power Products  
Division of Pullman Incorporated  
Attn: Mr. R. E. Howard  
Vice President and General Manager  
Post Office Box 3308, Reach Road  
Williamsport, PA 17701

Gentlemen:

Thank you for your letter of May 14, 1979, in response to our letter dated April 23, 1979. As a result of our review, we find that additional information is needed relative to Item B, Notice of Deviation. Specifically, please describe what actions were performed with respect to Job No. 8087, Drawing F 204, to correct for the observed use of an unqualified welding procedure on Weld C.

Please provide this additional information within twenty (20) days in order that we may complete our review in a timely manner.

Sincerely,

Uldis Potapovs, Chief  
Vendor Inspection Branch

606119

79988900

7908100104