



August 6, 1979

MP-1- 1275


Mr. Boyce H. Grier
Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Provisional License DPR-21
Docket No. 50-245
Reportable Occurrence RO-79-19/3L

Dear Mr. Grier:

This letter forwards Licensee Event Reports for Reportable Occurrence RO-79-19/3L. These reports provide information with regard to local leak rate testing performed during the 1979 refueling outage. An additional three copies of the reports are enclosed.

Yours truly,


J. F. Opeka
Station Superintendent
Millstone Nuclear Power Station

JFO/KT:11m

Attachment: (LER RO-79-19/3L and Attachment - Report)

cc: Director, Office of Inspection and Enforcement, Washington, D.C.
(30)
Director, Office of Management Information and Program Control,
Washington, D.C. (3)

POOR ORIGINAL

598346

790 8100 445