



Commonwealth Edison

Zion Generating Station
Shiloh Blvd. & Lake Michigan
Zion, Illinois 60099
Telephone 312/746-2084

DAK

July 26, 1979

Mr. James G. Keppler
Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
Glen Ellyn, Illinois 60137


Reference: Zion Generating Station
Docket No. 50-295/DPR-39
Technical Specification, Section 6.6.2

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/79-50 for Zion Generating Station. This occurrence was reported to Region III, Directorate of Regulatory Operations by telephone on 7/17/79 and by telegram/mailgram on 7/17/79.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 6.6.2.a.(9) which states that discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition require a 14-day report.

Very truly yours,


N. E. Wandke
Superintendent
Zion Station

Enclosure: Reportable Occurrence Report No. 50-295/79-50

A002
S/11
JUL 30 1979

7908146
557
S

627311